

STRUCTURAL MAINTENANCE SCHEMES 2017 2018 - Drainage

Project No	Project Type	Bedford Borough Scheme Name	Description & Location	Council Info		Programme Info	
				Borough Council Ward	Town or Parish	Planned	Completed
C1849	Drainage Maintenance	Bromham Road	Install length of new 200m carrier drain within the carriageway to alleviate surface water flooding	Bromham and Biddenham	Biddenham	Jan-18	29/03/2018
C1848	Drainage Maintenance	Grange Lane, Bromham	Repair a 20 metre length of carrier drain within the grass verge	Bromham and Biddenham	Biddenham	May-17	01/05/2017
C1837	Drainage Maintenance	Victoria Road/Kempston Road junction	Installaiton of two new gullies to reduce surface water flooding at pedestrian crossing locations	Kempston C & E Ward	Kempston	Jun-17	01/06/2017
C1842	Drainage Maintenance	Church End, Biddenham	Recent extension to property appears to have destroyed the drainage run. This has led to the property experiencing flooding. Gulley will require diverting...possibly to a new soakaway	Bromham and Biddenham	Biddenham	Oct-17	01/10/2017
C1844	Drainage Maintenance	High Street, Pavenham	Surface water is not being intercepted by a gulley and has caused property level flooding	Oakley	Pavenham	Dec-17	01/12/2017
C1846	Drainage Maintenance	Radwell Road, Milton Ernest	A blocked gulley run has led to ponding surface water and this has flooded residential gardens	Sharnbrook	Milton Ernest	Oct-17	14/11/2017
C1847	Drainage Maintenance	Wellington Street	Additional drainage works post Tavistock Street	Harpur and De Parys	Bedford	May-17	01/05/2017
C1853	Drainage Maintenance	Silver Street, Great Barford	Carriageway ponding after extreme events	Great Barford	Great Barford	Oct-17	01/10/2017
C1834	Drainage Maintenance	Dean Grange Farm, Upper Dean	Pipe soakaway to watercourse to relieve ponding on carriageway	Riseley Ward	Upper Dean	Mar-18	15/03/2018
C1857	Drainage Maintenance	Eileen Wade Lower School, High Street, Upper Dean	Gulleys filling to run leading to water ponding in carriageway blocking access to school	Riseley Ward	Upper Dean	Mar-18	05/04/2018
C1858	Drainage Maintenance	Woburn Road Ditch, Kempston	Ditch clearance and regrading required to allow anglian water to carry out works to their pipes as potential flooding risk to property	Kempston West	Kempston	Jan-18	26/01/2018